


10

FIG. 1



START




FIG. 2

FIG. 3

82

72

16

88

ANSWER

Assembly Translator: U:\trans\test\demo\asm

十一

87

14 Hint: Translation accounts for clearing C bit
 24 Error: Cannot translate this line without knowing ARP value
 29 Error: Cannot translate this line without knowing ARP value
 40 Hint: Supply DBMR value to improve translation
 (56) Warning: Translation assumes NDX is 0

84 Ready

7
4
88

FIG. 4

16





FIG. 5






FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 13




FIG. 12

FIG. 14




FIG. 15




FIG. 16




FIG. 17





FIG. 18







FIG. 19A



TO FIG. 19B

TI-28475
14 of 15

FROM FIG. 19A





FIG. 19B



TI-28475
15 of 15

FIG. 20

